




Assembly Instruction




NO.	QTY.	LINEDRAWING	DESCRIPTION
(A)	28		
(B)	28		
(C)	28	 Ø8*40	
(D)	12	 Ø7*50	
(E)	6		
(F)	3		
(G)	12	 Ø3*14	
(H)	5		
(I)	3		
(J)	3		
(K)	5		
(L)	5	 Ø3.5*35	
(M)	30		

PARTS LIST




NO.	QTY.	LINEDRAWING	DESCRIPTION
①	1		
②	1		
③	2		
④	2		
⑤	1		
⑥	1		
⑦	1		
⑧	3		
⑨	1		
⑩	2		
⑪	2		


1



2



3



4

