



836-109











OPERATING INSTRUCTIONS



■Part List





 X2	 X2	 X4	 X1
	 X1	 X2	
 X1	 X1	 X1	 X1








11 X1	12 X3	13 X4	
14 X2	15 X2	16 X2	17 X2
18 X2	19 X2	20 X1	21 X1



PART	QTY.	ITEM	
A	12	3X15 MM	
B	22	6X40 MM	
C	8	6X15 MM	
D	6	6X25 MM	
E	8	5X55 MM	
F	2	4X20 MM	
G	20	3X12 MM	
H	8	4X35 MM	




PART	QTY.	ITEM	
I	4	Φ 14-Φ 9X3 MM	
J	4	Φ 16 MM	
K	22	Φ 15 MM	
L	8	8X30 MM	
	1		








■ Assembly Instructions


1

**A** 3X15 MM
x4

2

**A** 3X15 MM
x4



3

**A** 3X15 MM

x4



4

**B** 6X40 MM



x4

K Φ 15 MM

x4



5

**B** 6X40 MM




x4

K Φ 15 MM

x4



6

**B** 6X40 MM

x8




**K** Φ 15 MM

x8

**L** 8X30 MM

x6

7

**B** 6X40 MM

x6

**K** Φ 15 MM


x6

**L** 8X30 MM


x2




8




9

**C** 6X15 MM x4**I** $\Phi 14 - \Phi 9 \times 3 \text{MM}$  x4


10



11



**D** 6X25 MM x4**J** Φ 16MM x4

12



**E** 5X55 MM x8





13

**G** 3X12 MM x8



14

**H** 4X35 MM x8


15




16

**C** 6X15 MM x4**F** 4X20 MM x2


17

**D** 6X25 MM x2

18

**G** 3X12 MM x8

19

**G 3X12 MM****x4**

20

