






837-019



E 16x 	F 5x 	G 6x 	H 3x14 6x 
A 16x 	B 16x 	C 14x 	D 7x50 4x 


1

D		7x50
		4x
C		2x




2


C		4x
B		8x
A		8x



3



4



C		8x
B		8x
A		8x

5



H
3x14



G

6x




Diagram showing the assembly of a rectangular frame. Screws are being inserted into the corners. Labels G*6 and H*6 point to the screws being installed.

6



F

5x




Diagram showing the assembly of a rectangular frame. Screws are being inserted into the corners. Label F*5 points to the screws being installed.

7



E

16x




Diagram showing the assembly of a rectangular frame. A panel is being attached to the frame. Label 9 points to the panel. Label E*16 points to the screws being installed.