


*kleanfin*

INcve030\_GL

**834-329**




IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY

**ASSEMBLY & INSTRUCTION MANUAL**


A x 1



B x 1




C x 1



D x 2




E x 1




F x 1




G x 1




H x 1




I x 1




J x 2



K x 1




L x 2




M x 1




N x 3




O x 1




**a** x28



**b** x28




**c** x30



**d** x 4  
M4\*35




**e** x13  
M3\*12




**f** x 1




**g** x 2




**h** x 1  
M4\*16




**i** x 1




**j** x 1




**k** x 4



**l** x18  
M2\*10




**m** x 1




**n** x 1  
M4\*40




**o** x 1







**p** x 1







ax24






bx16 cx8




 cx2    dx4









 bx4    cx4




	ax4		ex2		jx1
---	-----	---	-----	---	-----






	ex6		fx1		gx2		hx1		ix1
---	-----	---	-----	---	-----	---	-----	---	-----





	bx2		cx6
---	-----	---	-----






	bx2		cx6
---	-----	---	-----








-  bx4
-  cx4





-  lx18
-  ex1
-  mx1



 ex4



 kx4

- |   |     |   |     |   |     |
|---|-----|---|-----|---|-----|
|  | nx1 |  | ox1 |  | px1 |
|---|-----|---|-----|---|-----|

