



















# PawHut® D51-088 Assembly Instructions


-  A 3.5\*40 22PCS
- B 3.5\*50 4PCS
- C 3.0\*38 4PCS
- D 3.5\*30 4PCS
- E 3.5\*20 2PCS
- F 3.0\*12 12PCS
-  2PCS
-  8PCS




STEP1




STEP2




STEP3




STEP4







STEP5




STEP6




STEP7



STEP8



STEP9



STEP10