


PawHut!

INdhc010_GL


D30-456




IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY

ASSEMBLY & INSTRUCTION MANUAL


PARTS



1 x01



2 x01




3 x01




4 x01



5 x01




6 x01




7 x02


HARDWARE




A x01
M8*50




B x02
M6*30




C x04
M3*25
+1(spare)



D x01
M8*50



E x04
M38
+1(spare)



F x01
M5

A x01
M8*50

B x02
M6*30

C x04
M3*25

D x01
M8*50

E x04
M38

