





GL C000000


84C-171




ASSEMBLY INSTRUCTION




A 4x



B 4x



C 4x



F 4x



G 4x



I 4x




J 4x



L 4x




M 4x



N 12x




O 8x



P 8x



Q 4x



R 4x



U1 8x



U2 8x



M6*15

X1 128x




M6*40

X2 16x




M6*30


X3 16x




X4 12x




1 4x




2 4x




4 4x



5 4x



6 4x




7 8x




8 4x




10 4x




12 4x



13 1x



14 1x



15 4x



16 4x




18 8x



20 144x



21 5x




S4

1x

REQUIRED TOOLS



<1>



A 4x




8 4x









X1 8x




20 8x



<2>





N 4x



10 4x




M6*15

X1 32x






20 32x





<3>




6




<4>





<5>







7



<6>




<7>






M 4x



6 4x



13 1x




X1 12x
M6*15



20 12x

<8>




X1 12x
M6*15



20 12x

<9>



9



L 4x





M6*15

X1 8x



20 8x

<10>




14 1x













21 1x


<11>





10

<12>

-  **1** 4x
-  **2** 4x
-  **4** 4x
-  **5** 4x
-  **F** 4x
-  **G** 4x
-  **I** 4x
-  **J** 4x
-  **Q** 4x
-  **R** 4x



11

-  **X1** 8x
-  **20** 8x

<13>



15 4x




16 4x










18 8x




21 4x




































X4 12x







12



Carton-1/3	No	Reference Picture	Part	Qty
	1		A	4
	2		L	4
	3		M	4
	4		N	12
	5		8	4
	6		10	4
	7		6	4
Carton-2/3	No	Reference Picture	Part	Qty
	1		B	4
	2		C	4
	3		F	4
	4		G	4
	5		I	4
	6		J	4
	7		O	8
	8		P	8
	9		Q	4
	10		R	4
	11		U1	8
	12		U2	8
13	13	 M6*15	X1	128
	14	 M6*40	X2	16

Carton-2/3	No	Reference Picture	Part	Qty
	15	 M6*30	X3	16
	16		X4	12
	17		7	8
	18		12	4
	19		13	1
	20		14	1
	21		15	4
	22		16	4
	23		18	8
	24		20	144
	25		21	5
	26	S4 		1

Carton-3/3	No	Reference Picture	Part	Qty
	1		1	4
	2		2	4
	3		4	4
	4		5	4
14				

US



001-877-644-9366
customerservice@aosom.com

CA



001-855-537-6088
customerservice@aosom.ca

UK



0044-800-240-4004
enquiries@mhstar.co.uk

DE



0049-(0)40-88307530
service@aosom.de

FR



0033-1-84166106
contact@aosom.fr

ES



0034-931294512
atencioncliente@aosom.es

IT



0039-0249471447
clienti@aosom.it