


IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY

Tools Recommended

## ASSEMBLY & INSTRUCTION MANUAL

**PARTS**

**1** x 8




**2** x 8



**3** x 8




**4** x 5




**5** x 5




**6** x 5



**7** x 2




**8** x 2



**10** x 4




**12** x 4



**HARDWARE**

**H** x20  
M6\*45  
+1(spare)



**K** x20  
+1(spare)



**A** x10  
+1(spare)



**B** x 4




**C** x 4




**D** x 1




- 1 x4
- 2 x4
- 5 x1
- 6 x1
- 10 x2
- A x1
- H x2
- K x2




- 3 x4
- 5 x4
- 6 x4
- 7 x1
- 8 x1
- 12 x2
- A x4
- H x8
- K x8



- 1 x2
- 2 x2
- 3 x2
- 4 x5
- 10 x1
- 12 x2
- H x5
- K x5



- 1 x2
- 2 x2
- 3 x2
- 7 x1
- 8 x1
- 10 x1
- A x5
- H x5
- K x5



- B x4
- C x4
- D x1

