


















INbya020_GL

845-707




READ AND SAVE THIS INSTRUCTIONS FOR FUTURE USE


ASSEMBLY & INSTRUCTION MANUAL

	① x1		⑧ x2
	② x1		⑨ x2
	③ x1		⑩ x2
	④ x1		⑪ x1
	⑤ x2		⑫ x2
	⑥ x3		⑬ x1
	⑦ x1		⑭ x0

15 x1



F x02(spare)




M6*60

16 x2




A x07+1(spare)




M6*45

B x08+1(spare)




M3.5*35

C x30+2(spare)





M3*30


D x12+1(spare)



M3.5*25

E x1(spare)






Dx03

M3.5*25




2x01



3x01


3



2


D

D




Cx04


M3*30



14x01



16x02




16

C

C


14

Ax04




M6*45

Fx02




M6*60


6x03




6




Ax03



M6*45






Dx03


M3.5*25





1x01





5x02




7x01



Ex01





Dx06




M3.5*25

4 x01




Cx22




M3*30


12x02





8 x02




9 x02




10x02




Bx02




M3.5*35




Bx02



M3.5*35




Bx02




M3.5*35


11x01




11




Bx02



M3.5*35




Cx04



M3*30

13x01



15x01

