




# MOUNTING INSTRUCTIONS








## Sit and Stand Desktop




### Features & Specifications






### Components

	A	B	C	D	E	F	G
1							
			X6	S=4mm	X1	X2	X4 X2

Tools required not included







1




**Warning: Impact Hazard! Moving Parts can Crush and Cut.**


2



3



4





**!** Keep monitor and laptop base fully on the worksurface. Allowing any part of base or stand to hang off the edge may result in property damage and/or personal injury.




**!** Raise worksurface slowly. Raising worksurface too fast may create an unstable situation resulting in property damage and/or personal injury.



5



6



The load of the desk can be adjusted. Turn clockwise to reduce the load and counter-clockwise to increase the load.



**!** Leave enough slack in cable to allow for full range of vertical motion (15" / 38 cm). Failure to heed this warning may result in property damage and/or personal injury.



**!** To avoid the potential to pinch cables it is important to follow the cable routing instructions in this manual. Failure to follow these instructions may result in equipment damage or personal injury.



**WARNING**

**PINCH POINT**

DO NOT place hands on or near support bars. Pinch points are created during lifting and lowering the worksurface. Failure to follow these instructions may result in serious personal injury.

