












A×30	B×3	C×3	D×26	E×18	F×26
 3×12mm					
G×4	H×4	I×20	K×1	M×3	N×12
 4×40mm		 4×14mm			 4×30mm
O×3	P×3	Q×8	R×8	S×1	
			 3×14mm		

1




A×18	B×3	C×3	D×4
 3×12mm			

2




E×4	F×4
	




E × 4	G × 4
	
	4 × 40mm


4





5




6

 $D \times 4$ 


7

 $K \times 1$ 




E×4	F×4

9




D×15	E×3	F×15	M×3
			

10



D×3	E×3
	


11



× 3

F × 3	N × 12
	
	4 × 30mm


12




× 3

A × 12	O × 3	P × 3
		
3 × 12mm		


13



14



Q×8	R×8
	
	3×14mm



S×1

