


PawHut®

INdba054_GL


D30-496




IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY

ASSEMBLY & INSTRUCTION MANUAL

PARTS




HARDWARE



01


① x1 ② x1

Ⓐ x2




02

⑤ x1 Ⓐ x2




⑥ x1 ① x4

03




③ x1 ① x4

04



E x 2

05





7 x 1

B x 2



F x 1

06



⑧ x1 ③ x2


⑥ x1



④ x1 ③ x2

⑨ x1


④



A x4

09


7 + 8



9 x1 **J** x2


10

I x2




⑩ x1 ③ x2 ④ x2

11




⑩ x1 ③ x2 ④ x2

12



11 x 1 D x 2


13



D x 4

14

9 + 13



12 x 1 C x 4

D x 4 K x 1

