



# PawHut®












D02-032




Please read these instructions and warranty information carefully before use and keep them properly for future reference.

OPERATING INSTRUCTIONS




A	 <b>M6*45</b>	8PCS	B	 <b>3.5*25</b>	8PCS
C	 <b>3*25</b>	8PCS	D	 <b>3*20</b>	4PCS
1		1PC	4		2PCS
2		1PC	5		4PCS
3		2PCS	6		2PCS
			7		1PC


1 A M6\*45 4PCS




2 A M6\*45 4PCS




3 B 3.5\*25 8PCS



4 C 3\*25 4PCS



5 C 3\*25 4PCS



6 D 3\*20 4PCS

