





IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY

ASSEMBLY & INSTRUCTION MANUAL



① x1




② x1




③ x4


A x 4
 M8*40
 +1(spare)

B x 4
 +1(spare)
**C** x 1

③ x4

A x4**B** x4

② x1



Done

